Freese et al.

PLUNGE-TYPE ROUTER HAVING IMPROVED PLUNGE...

Greer, Burns & Crain, Ltd. (Roger D. Greer)

Our File 0212.68529

Sheet 1 of 6 (312) 360-0080




FIG. 1

Freese et al.

PLUNGE-TYPE ROUTER HAVING IMPROVED PLUNGE...

Greer, Burns & Crain, Ltd. (Roger D. Greer)

Our File 0212.68529

Sheet 2 of 6

(312) 360-0080




FIG. 2 (PRIOR ART)

Freese et al. 3-11-04
PLUNGE-TYPE ROUTER HAVING IMPROVED PLUNGE...
Greer, Burns & Crain, Ltd. (Roger D. Greer)
Our File 0212.68529
Sheet 3 of 6 (312) 360-0080




FIG. 3 (PRIOR ART)

Freese et al. 3-11-04
PLUNGE-TYPE ROUTER HAVING IMPROVED PLUNGE...
Greer, Burns & Crain, Ltd. (Roger D. Greer)
Our File 0212.68529
Sheet 4 of 6 (312) 360-0080




FIG. 4

Freese et al. 3-11-04
PLUNGE-TYPE ROUTER HAVING IMPROVED PLUNGE...
Greer, Burns & Crain, Ltd. (Roger D. Greer)
Our File 0212.68529
Sheet 5 of 6 (312) 360-0080




FIG. 5

Freese et al.

PLUNGE-TYPE ROUTER HAVING IMPROVED PLUNGE...

Greer, Burns & Crain, Ltd. (Roger D. Greer)

Our File 0212.68529

Sheet 6 of 6 (312) 360-0080




FIG. 6